

From: "Goncalves, Kathleen" <Kathleen.Goncalves@rolls-royce.com>
Date: December 28, 2015 at 4:24:44 PM EST
To: JC Walker <jcwalker@paradigmjet.com>
Cc: Jeff Spyke <jeff@paradigmjet.com>, Josh Wade <josh@paradigmjet.com>
Subject: RE: ext request

Hi Jeff

As this is a chapter 5 requirement we are unable to provide an extension.

I have looked at your attached sheet and I am not quite sure how they arrived at these numbers. The requirement is every 1000 hours with a +/- 100 hour window. If this was last done at 7111 hours I am not sure how they came up with a reinspect at 8195 hours. Perhaps this is due to a lease engine having been installed previously? If that is the case perhaps this was addressed when the engine was in the shop?

Best Regards,

Kathleen Goncalves

Regional Customer Manager