

(11)

CONCLUSION: NARRATIVE

(11) The possible reason
(RIGHT FENDER LINKER) came off
of my car on a freeway

BETWEEN ORANGE ST. AND
MOUNTAIN VIEW, REDLANDS CALIFORNIA

(1) WRONG SUB-FRAME?

(2) WRONG (RIGHT - FENDER LINKER)?

PART NUMBER: 74101TR3A50

REFERENCE NUMBER: U0120203

(3) OR THE (RIGHT (FENDER LINKER))
NOT PROPERLY INSTALLED?

(4) RIGHT FENDER LINKER, INSTALLED
ON MY 2013 HONDA CIVIC
WAS A DEFECTIVE PART.

(5) WISH SPEAK HONDA ORDER
ME ANOTHER: (RIGHT FENDER LINKER)

RATHER OF CHARGE I POSSIBLY DRIVE
WITH PART TO ANOTHER CAR DEALER SHOP. FOR FEAR
POSSIBLE RETALIATION MAKING COMPLAINT. LABOR CODE: 6310