

Repair Estimate

PREPARED FOR
JOHN DAY
(575) 993-7879

Service Advisor
Tabbitha Sosa (149340)
tsosa@Group1Auto.com

Date 12/18/2023 03:26 PM
2023 Subaru OUTBACK
VIN 4S4BTGUD9P3110345
Mileage 8,496
RO# 194073

Service Name	Price
[Primary]: DIAG : OTHER DIAGNOSIS C/S: CUSTOMER STATES SHE WAS IN A CAR ACCIDENT AND WOULD LIKE TO GET THE VEHICLE INSPECTED AFTER COMING OUT OF THE BODY SHOP. PLEASE CHECK AND ADVICE.	\$0.00
[Primary]: MENU : MENU SUBARU FACTORY MULTI-POINT INSPECTION	\$0.00
[Other]: UPON INSPECTION FOUND TPMS LIGHT ON. FOUND CODE FOR ABNORMAL AUTOMATIC ID. RECOMMEND TO PERFORM A TPMS RELEARN.	\$177.05
*Subaru – Cabin Air Filter Replacement: REPLACE CABIN/POLLEN AIR FILTER. \$44.99 PLUS TAX.	\$44.99
Wheel Bearing Replacement - Front: UPON INSPECTION FOUND FRONT LEFT WHEEL BEARING MAKING ABNORMAL NOISE. RECOMMEND REPLACEMENT OF FRONT LEFT WHEEL BEARING.	\$836.75
Wheel Bearing Replacement - Rear: UPON INSPECTION FOUND REAR LEFT WHEEL BEARING MAKING ABNORMAL NOISE. RECOMMEND REPLACEMENT OF REAR LEFT WHEEL BEARING.	\$818.25
Printed on December 18, 2023	
Quote expires on January 17, 2024	

Subtotal	\$1877.04
Shop Charges	\$39.00
Tax	\$49.82
Total	\$1965.86



Subaru El Paso
1444 Airway Blvd.
El Paso, TX 79925

9154013200