



Dashboard

Payments

Special
Offers

Maintenance
Articles

Seasonal
Checklist

Request S

< [Back to Dispatch: #329699188](#)

Non-Covered Cost Estimate

18 RENO CV

You have 1 estimated non-covered cost associated with your service request.

To proceed with your service request, **accept** the estimated non-covered costs. Then call North Pulaski Heat & Air Co. L.L.c. at (501) 515-2021 to complete the service.

Non-Covered Costs Details



Central Heating & A/C System		Cost
Replace	Evaporator Coil	\$2070.00
Failure Reason	Age	
Contractor Note	Tech found no refrigerant in unit after replacing control board; tech found leak in the evaporator coil; unit is unable to cool	
Replace	Control Board / Panel	ⓘ TBD
Failure Reason	Normal wear & tear	
Contractor Note	The control board is shorted , causing the furnace to not heat	
Replace	AHS Supply Evap Coil	ⓘ TBD
Failure Reason	Normal wear & tear	
Contractor Note	ahs	



- [Dashboard](#)
- [Payments](#)
- [Special Offers](#)
- [Maintenance Articles](#)
- [Seasonal Checklist](#)
- [Request Service](#)

Contractor Note	tax on ncc	
Replace	repair credit	ⓘ TBD
Failure Reason	Normal wear & tear	
Contractor Note	repair credit	

Total estimated non-covered costs

\$2266.65

*American Home Shield cannot guarantee the accuracy of this estimate. For exact costs, contact the contractor.