

(6)

NARRATIVE

DRIVE TO SPREEN Honda, Loma Linda
25050 Redlands Blvd, Loma Linda
CALIF 92354

ARRIVED APPROXIMATELY 07:30 A.M.

ALL WORK SUPPOSEDLY COMPLETED

AT: 1:12 P.M. OUT - Side employee
HAD HARD TIME FINDING MY CAR AT
FIRST. CAR NOT TAGGED.

SUPPOSEDLY ALL THIS WAS DONE FOR MY
2013 Honda Civic.

(1) REPLACED (SUB-FRAME) WITH EXACT
MANUFACTURER PART FOR MY 2013 Honda Civic
VIN: NUMBER: 19XFB2F53DE219860

(2) NOTE: NOT PARTS SHOULD HAVE FELL OFF CAR
UNLESS WRONG CAR PART

(3) OTHER WORK SUPPOSEDLY DONE SPREEN Honda:

(4) INSTALL CONTROL ARM. (5) Heat Shield. (6)

INSPECT CAR STRUTS. (7) CAR ALIGNMENT.

(8) INSTALL BRAND NEW: (RIGHT FENDER LINER)

PART NUMBER: 74101TR3A80

REFERENCE NUMBER: U0120203