

④ NARRATIVE

These are areas of damage for parts and labor, according to: SERVICE ADVISOR:

Johnny Torrez. OF SPREEN Honda, Loma Linda
25050 Redlands Blvd, Loma Linda CALIF 92354
Phone: (909) 799-7070

NOTE: The Blue Book value car is: \$8,000.00
2013 Honda Civic. 4 door LX, Automatic.

- (1) must repair or replace (SUB-FRAME).
- (2) must replace control arm.
- (3) must replace heat shield
- (4) must have car struts inspected for damage.
- (5) car must have a car alignment.

(6) I paid for (RIGHT FENDER LINER)



THIS PART GO'S OVER CAR TIRE
to protect, hoses, and electrical wires

Reference Number: V012 02 03

PART NUMBER: 74101 TR3A50

NOTE: JUST PRIOR TO FRIDAY FEB 3, 2023.

A SPREEN Honda employee informed me that
mechanics could not install (RIGHT FENDER LINER)
BECAUSE THE (SUB-FRAME) on my car
WAS BENTED. Holes would not match. They
MIGHT BE ABLE TO PUT ON. YET IF I DRIVE HIGH
SPEED ON PREWAY, PART WILL FLY OFF. I declined instal.