

(12)


SPREEN HONDA
SUSPICIOUS BEHAVIOR
AND COMMENTS MADE
BY SERVICE ADVISOR:
Johnny Torrez.

① NOTE:

WHILE DRIVING WEST BOUND ON 10 FREEWAY
FROM, ORANGE ST. TO MOUNTAIN VIEW,
I WAS DRIVING APPROXIMATELY 55 M.P.H. OR
60. (RIGHT FENDER LINER) CAME OFF OF
CAR. WENT UNDER CAR ON FREEWAY. (RIGHT
FENDER LINER) FLEW TO RIGHT SIDE FREEWAY.
NOTE: THIS FAULTY PART COULD HAVE CAUSED ME
TO GET IN A ACCIDENT OR OTHER DRIVER
TO HAVE A ACCIDENT. NOTE: I WAS DRIVING
ON NUMBER 3, LONG FREEWAY. ON FEB
3, 2023 AFTER 1:00 P.M. BETWEEN
ORANGE ST. AND MOUNTAIN VIEW CITY
OF REDLANDS.

② AFTER (RIGHT FENDER LINER) CAME OFF CAR,
DROVE BACK TO SPREEN HONDA

REDLANDS BLVD



③ SERVICE MANAGER:
Johnny Torrez. NO ONE
KNOW WHERE HE MYSTERIOUS
WENT. THE MANAGER ASKED ADULT
SERVICE MANAGER CLAIMED
Johnny Torrez won't be back
FOR 45 MINUTES. MOST PEOPLE
ONLY GET 30 MINUTE LUNCH BREAK.