

(14)


SPREEM HONDA

SUSPICIOUS BEHAVIOR:

SERVICE ADVISOR: JOHNNY TORRES

(1) THE STATION, HE WENT TO LUNCH. HE NEVER SHOWED ME A RECEIPT OF WHERE HE WENT TO LUNCH. SO IN REALITY, HE KNEW (RIGHT FENDER LINER) WAS GOING TO COME OFF ON REG WY

(2) SERVICE ADVISOR: JOHNNY TORRES, LIES. HE STATED TIRE (RIGHT FENDER LINER) COULD NOT BE ORDERED, IT IS A BACK ORDERED PART. REFERENCE NUMBER: VO120203. PART NUMBER: (74101TR3A50)



(RIGHT FENDER LINER) GOES UP AROUND TIRE TO PROTECT WHEELS

(3) JIM OF PARTS ORDERED ME ANOTHER: (RIGHT FENDER LINER)

(4) NOTE: (RIGHT FENDER LINER) WILL FALL OFF CAR FOR ~~THIS~~ THESE REASONS:

(1) DEFECTIVE (RIGHT FENDER LINER) (2) WRONG SUB FRAME

(3) WRONG (RIGHT FRONT FENDER LINER).

(5) NO SPREEM HONDA SHIPPING MANIFEST OR ANY PAPER WORK SHOWS ANY BRAND NEW, (SUB-FRAME) ONLY SUB-FRAME USED. FROM: STAFF- FROM / CAR INSURANCE. PURCHASED FOR \$145.00 SO WHY SPREEM HONDA CHARGE \$3,000.00 PARTS + LABOR ??