

DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app




INDEPENDENT MECHANIC INSPECTION REPORT

CAR: 2010 Chrysler Sebring L4-2.4L Odometer: 51094

VIN: 1C3BC4EB8AN113219 Report Created: 2/25/2020 @ 3:18PM

YourMechanic Score



	Poor	⊦air	Good	Very Good	Excellent
Dash					•
Tires					•
Fluids					•
Brakes					0
Engine					0
Other					•

Mechanic

Hugo Galdamez

About Hugo

Specialties







DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app



DASH

Dash Lights	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Warning Lights					No Warning Light is on

TIRES

Tire Pressure Measurement	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Driver Side Front				•	32 psi
Passenger Side Front				•	32 psi
Driver Side Rear				•	32 psi
Passenger Side Rear				•	32 psi

Tire Treading	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Driver Side Front				•	7/32"
Passenger Side Front				•	7/32"
Driver Side Rear				•	7/32"
Passenger Side Rear				•	7/32"
Spare Tire				•	10/32"

FLUIDS

Engine Oil	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Engine Oil Level				•	Normal
Engine Oil Condition				•	Yellow
Transmission Oil	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Transmission Oil Level				•	Normal
Transmission Oil				•	Pink
Condition					

DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app



Brake Fluid	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Brake Fluid Level				•	Normal
Brake Fluid Condition				•	Yellow
Coolant	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Coolant Level				•	Normal
Coolant Condition				•	New
Power Steering Fluid	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Power Steering Fluid Level				•	Normal
Power Steering Fluid Condition				•	Normal
Washer Fluid	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Washer Fluid Condition				400	Normal

BRAKES

Pads	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Driver Side Front				•	10mm
Passenger Side Front				•	10mm
Driver Side Rear				•	Brake Pad Not Accessible/Visiblemm
Passenger Side Rear				•	Brake Pad Not Accessible/Visiblemm
Rotors	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Driver Side Front					Warped
Passenger Side Front				•	No Visible Problem



DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app



ENGINE

Cooling System	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
All Cooling System					ОК
Components					
Belts	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
All Belts				•	ОК
Engine Mounts	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Left					OK
Right				•	ОК
Front				•	OK
Rear					OK
Torque Rod					OK
Torque Trou					
Torque flou					
Transmission Mounts	Poor	Fair	Good		
·	Poor	Fair	Good	Very Good Excellent	
Transmission Mounts Left	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic OK
Transmission Mounts	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Transmission Mounts Left	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic OK
Transmission Mounts Left	Poor	Fair Fair	Good	Very Good Excellent	Notes & Advice from Mechanic OK
Transmission Mounts Left Right				Very Good Excellent	Notes & Advice from Mechanic OK OK
Transmission Mounts Left Right Air Filter				Very Good Excellent Very Good Excellent	Notes & Advice from Mechanic OK OK Notes & Advice from Mechanic
Transmission Mounts Left Right Air Filter				Very Good Excellent Very Good Excellent	Notes & Advice from Mechanic OK OK Notes & Advice from Mechanic
Transmission Mounts Left Right Air Filter				Very Good Excellent Very Good Excellent	Notes & Advice from Mechanic OK OK Notes & Advice from Mechanic OK

OTHER

Battery	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Corrosion					Not Accessible
Case Leaking				•	No Leak



DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app



Windshield Wipers/Motors	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Front Driver Wiper Condition					No Visible Problem
Front Passenger Wiper Condition				•	No Visible Problem
Front Windshield Wiper Motors					All Operational
Seat Belt	Poor	Fair	Good	Very Good Excellent	Notes & Advice from Mechanic
Operation Problem				•	All Operational



DOWNLOAD THE APP Scan the QR code or visit YourMechanic.com/app



ABOUT YOURMECHANIC.COM INDEPENDENT MOBILE MECHANICS

YourMechanic.com is a network of Certified & Independent mobile mechanics (mechanics who come to your home or office to fix or inspect your

Download our FREE mobile app to:

- · See maintenance schedules for your car
- · Find fair prices for repairs & maintenance
- See recalls and TSBs for your car · Manage service history
- · Book appointments with certified mechanics

AS SEEN ON: OCBS 4 NBC TechCrunch Forbes Inc.

Condition Definitions

Like new, well maintained and requires no repair. Excellent

No detectable defect, wear consistent with the age and mileage. Very Good

Good No major defect, minor problems present.

Will require maintenance or repair in next 3-6 months.

Some problems require immediate repair or maintenance. Fair Poor