



25050 Redlands Blvd Loma Linda California 92354

(909) 799-7070

BAR# AC-108265 EPA# CAD-982318552 DLR# 20-7523



1080 Pomona Road Corona, California 92882

(951) 281-1080

BAR# ARD-297460 EPA# CAL-000454734 DLR# 03680

1

POSSIBLE?
LIPR.
LOW - ARTIST.?

THIS FORM IS AN ITEMIZED LIST OF REPAIRS AND IS PART OF A REPAIR ORDER. THIS REPAIR ORDER CONTINUATION IS SUBJECT TO ALL THE CONDITIONS OF THE ORIGINAL REPAIR ORDER.

NOTICE TO CONSUMER: PLEASE READ
IMPORTANT INFORMATION

CELL 909-602-2169

CUSTOMER NO. 209400	ADVISOR JOHNNY TORREZ 01099	TAG NO. 3310	INVOICE DATE 02/03/23	INVOICE NO. HOC5988290
RUDY MURILLO 25745 BARTON RD #421 LOMA LINDA, CA 92354	LABOR RATE	LICENSE NO.	MILEAGE 81,924	COLOR
RUDE.MURILL@YAHOO.COM	YEAR / MAKE / MODEL 13/HONDA/CIVIC SDN/4DR SDN LX AT	VEHICLE I.D. NO. 19XFB2F53DE219860	DELIVERY DATE	DELIVERY MILES
RESIDENCE PHONE	F.T.E. NO.	P.O. NO.	SELLING DEALER NO.	PRODUCTION DATE
BUSINESS PHONE	COMMENTS	R.O. DATE 01/25/23		

MO: 81924

LABOR
J# 1 25HOZ1MPI MULTI POINT INSPECT HOURS: TECH(S):741 0.00

CUSTOMER REQUEST TO PERFORM MULTI POINT INSPECTION/
TCPA (TELEPHONE CONSUMER PROTECTION ACT)
" I CONSENT TO BEING CONTACTED CONCERNING THIS REQUEST FOR
THIS SERVICE AT ANY CELLULAR OR MOBILE TELEPHONE NUMBER,
EMAIL ADDRESS, OR OTHER TELEPHONE NUMBER I HAVE PROVIDED
OR WAS PROVIDED ON MY BEHALF, INCLUDING TELEPHONE CALLS,
PERFORMED MULTI POINT INSPECTION CHECK LIST REPORT

J# 2 04HOZAIRPRESS WHEELS & TIRES HOURS: TECH(S):741 0.00

ADJUST AIR PRESURE TO MANUFACTURES SETTINGS.
ADJUST AIR PRESSURE TO MANUFACTURES SETTINGS.
FRONT RIGHT PSI
FRONT LEFT PSI
REAR RIGHT PSI
REAR LEFT PSI

J# 3 62HOZMISC STEERING MISC HOURS: TECH(S):741 1535.64

CUSTOMER STATES HE HIT SOMETHING AND DAMAGED SUB FRAME SOP
CONTROL ARM FENDER LINER AND PERFROM ALIGNMENT AND INSPECT
FRONT STRUTS
OUTSIDE DAMAGE HIT A CURB
REMOVED AND REPLACED LOWER SUB FRAME AND PASSENGER FRONT
CONTROL ARM, PASSENGER FRONT SIDE SPLASH SHIELD, LOWER
CENTER PIPE AND GASKET, AND PERFROMED 4 WHEEL ALIGNMNT
AS NEEDED

TOTAL - LABOR 1535.64

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 3	1	18220-TR6-A02	PIPE B, E	253.99	202.99	202.99
JOB # 3	1	18303-TR0-A01	GASKET, E	16.99	11.72	11.72
JOB # 3	1	74600-TR3-A00	PLATE A,	43.99	32.38	32.38
JOB # 3	1	51300-TX6-A01	SPRING, F	113.99	93.98	93.98
JOB # 3	4	90175-SSA-000	BOLT, FLG	12.99	12.48	49.92
JOB # 3	1	74101-TR3-A50	FDR, R. F	91.90	91.90	91.90
JOB # 3	10	91501-TR0-003	CLIP, FEN	3.99	3.99	39.90
JOB # 3	1	JE2902	GASKET	13.99	6.81	6.81
JOB # 3	1	10129179	CONTROL A	166.99	92.43	92.43
JOB # 3	1	50200-TR0-A02	SUB-FRAME	989.99	791.99	791.99
TOTAL - PARTS						1414.02

ESTIMATE-----

CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$2500.00 (+TAX)

APPROVED ADDITIONAL COST OF \$559.25 FOR TOTAL ESTIMATE OF \$3059.25 (+TAX) ON 02/03/23 AT 01:04p
BY INSURANCE COMMENTS FACTORY SUB FRAME